

Notes:

1) Pulse count should be 49440.

2) The speedometer and speed sensor do not share a power and ground circuit.

